

**Menu****HISTORY FILE MAP for year 2001**

Realtime


Playback

Recalled Realtime

Recalled Playback

129.18:29 – 18:36 DSS34 dropped lock  
going 2-way due to wrong template used  
("ACQ" instead of "XFER"). DR L05381.

130.20:04 – 20:14 DSS43 antenna halt due to accumulator pump failure.  
130.20:36 – 20:45 additional 1-way to 2-way. DR A05389



134.06:40 – 07:27 DSS63 complex-wide power glitch  
134.08:07 – 08:15 additional 1-way to 2-way caused  
by glitch. DR L05265.

134.18:18 – 18:31 DSS34 TX  
late at U/L transfer. DR A05401.